



Ground Floor Plan
Scale 1:100

NOTES		KEY	
	Wall plaster repair		Line out ceiling for service void (build-up depth indicated in box)
	Ceiling plaster repair		

TENDER ISSUE

<p>THE CONTRACTOR & HIS SUB-CONTRACTORS ARE TO VERIFY ALL DIMENSIONS ON SITE BEFORE MAKING SHOP DRAWINGS OR COMMENCING MANUFACTURE.</p> <p>THE CONTRACTOR & HIS SUB-CONTRACTORS ARE RESPONSIBLE FOR ENSURING THAT ALL PRODUCTS AND MATERIALS ARE INSTALLED CORRECTLY IN ACCORDANCE WITH MANUFACTURERS DETAILS, CURRENT BRITISH STANDARDS AND CODES OF PRACTICE.</p> <p>ANY DISCREPANCIES OR CONFUSION ARISING FROM INFORMATION PROVIDED IS TO BE REPORTED TO THE ARCHITECT PRIOR TO WORKS COMMENCING.</p> <p>THIS DRAWING IS COPYRIGHT</p>	<p>Rev A. Stud partition in Office removed - 29.11.19</p>	<p>Proposed alterations to: Fermina Fermain Lane St Martin for Mr and Mrs P. Briginshaw</p>	<p>WORKING DRAWING Repair Works Ground Floor</p>	Scale: 1:100	Date: November 2019
				<p>DWG No: 3530 - WD/09A</p>	

Chartered Architects & Interior Designers

Trafalgar House Petit Bouet St. Peter Port
Guernsey Channel Islands GY1 2AY
Tel (01481)726461
E-mail: mail@ccd-architects.com Web: www.ccd-architects.com