



NOTES

**KEY**

- Wall plaster repair
- Ceiling plaster repair
- Line out ceiling for service void (build-up depth indicated in box)

TENDER ISSUE

THE CONTRACTOR & HIS SUB-CONTRACTORS ARE TO VERIFY ALL DIMENSIONS ON SITE BEFORE MAKING SHOP DRAWINGS OR COMMENCING MANUFACTURE.

Rev. A. - Bathroom Layouts altered - 29.11.19

THE CONTRACTOR & HIS SUB-CONTRACTORS ARE RESPONSIBLE FOR ENSURING THAT ALL PRODUCTS AND MATERIALS ARE INSTALLED CORRECTLY IN ACCORDANCE WITH MANUFACTURERS DETAILS, CURRENT BRITISH STANDARDS AND CODES OF PRACTICE.

ANY DISCREPANCIES OR CONFUSION ARISING FROM INFORMATION PROVIDED IS TO BE REPORTED TO THE ARCHITECT PRIOR TO WORKS COMMENCING.

THIS DRAWING IS COPYRIGHT

Proposed alterations to:  
Feremina  
Fermain Lane  
St Martin  
for Mr and Mrs P. Briginshaw

WORKING DRAWING  
Repair Works  
First Floor

Scale: 1:100

Date: November 2019

DWG No:

3530 - WD/10A



Chartered Architects & Interior Designers  
Trafalgar House Petit Bouet St. Peter Port  
Guernsey Channel Islands GY1 2AY  
Tel (01481)726461  
E-mail: mail@ccd-architects.com Web: www.ccd-architects.com